

Operation Manual (Vibration Measurement)



July 20, 2021

ONOSOKKI

Table of Contents

1.	Introduction	1
1.1	Purpose of This Manual	1
1.2	Required Equipment	2
1.3	Notations Used in This Manual	3
1.4	Software Screen Configuration	4
1.4.1	Analysis Mode	5
1.4.2	Measurement Mode	6
2.	Equipment Connection Configuration Example	8
3.	Preparation for Measurement	10
3.1	Preparing Measuring Instruments and Starting Software	10
3.2	Creating New Project	12
3.3	Connecting DS-5000 with O-Solution	14
3.4	Setting Channels	16
4.	Unit Calibration	17
4.1	Setting Calibration	17
5.	Measurement Settings	19
5.1	Setting Time Axis Preprocessing	19
5.2	Setting Measurement	20
5.2.1	Setting Channels	20
5.2.2	FFT Basic Settings	21
5.2.3	FFT Average/ Detailed Settings	22
6.	Graph Display Settings	23
6.1	Changing Graph Layout	24
6.2	Displaying Channels in Graphs	25

6.3	Changing Data Types Displayed in Graphs	26
6.4	Setting Y Axis Display Unit and Scale	28
7.	Temporary Measurement	29
7.1	Setting Voltage Range	29
7.2	Performing Temporary Measurement	32
7.2.1	Starting/ Stopping Temporary Measurement	32
7.2.2	Adjusting Graph Scale	33
7.2.3	Saving Project	34
8.	Main Measurement	35
8.1	Toolbar Used in Main Measurement	35
8.2	Setting Data Save	36
8.3	Performing Main Measurement	37
8.4	Calculating Measurement Result	40
8.5	Registering Data in Analysis Data Manager	42
9.	Analysis Work	43
9.1	Switching to Analysis Mode	43
9.2	Integration (Conversion from Acceleration to Displacement)	44
9.3	FFT Analysis	46
9.4	Comparing Power Spectra	47
9.4.1	Overlaying Graphs	47
9.4.2	Checking Peak Value with Cursor	48
9.5	Drawing Time Trend Graph	49
10.	Saving Project	51
11.	Measurement Note	52

1. Introduction

1.1 Purpose of This Manual


This manual describes the general operation procedure for FFT vibration analysis using the O-Solution, OS-0522 FFT Analysis Function, and Accelerometer.

The procedures to obtain the averaging result of FFT analysis and perform recording for steady vibration measurement are provided.


This manual does not handle the vibration measurements such as impact vibrations generated in a hammering test, drop test, etc. and single shot vibration.

Performing the operations described in this manual brings the following results.

● Outputting Averaging Results of Three-Channel Power Spectra



● Outputting Various Graphs



1.2 Required Equipment

The following equipment is required for performing the operations described in this manual.

- **Hardware: DS-5000 Series Data Station**

Name	Details
DS-5100	Main Unit
DS-0523/0526	3ch/6ch 40kHz Input Unit*

* Use the Input Unit required for the number of measurement channels.

- **Software: O-Solution**

Name	Details
OS-5100	Platform
OS-0522	FFT Analysis Function
OS-0512	Hardware Connecting Function


1.3 Notations Used in This Manual



In this manual, the UIs displayed on the screen are enclosed in square brackets (example: [New project]). The operations are described in the following manner.

Operation	Notation
Left-clicking the mouse	Click or select Example: Click [○ ○]. Example: Right-click [○ ○] and select [○ ○].
Right-clicking the mouse	Right-click Example: Right-click [○ ○].
Dragging the mouse	Drag Example: Drag the displayed cursor up/down.
Double-clicking the mouse	Double-click Example: Double-click the icon.

1.4 Software Screen Configuration


The main window is displayed after the O-Solution is started. The main window is configured as shown below.



Item	Description
A	Title bar The software name and the active graph window name are displayed. Double-clicking on the title bar maximizes the window. Double-clicking in the maximized state restores the original size.
B	Close, maximize/undo, and minimize buttons Click to close, maximize/undo, or minimize the window.
C	Menu bar Used to execute the commands available on the O-Solution main window.
D	Mode switching Clicking the button switches the mode between the measurement and analysis modes.  : Switches to the measurement mode.  : Switches to the analysis mode.
E	Toolbar The quick access commands which can be used in each mode are displayed.
F	Window area The windows used for measurement and analysis are displayed. You can move a window to a desired location by drag-and-drop.


The windows used in the window area are intended for analysis and measurement as described in the following sections.

1.4.1 Analysis Mode



	Window name	Description
a	Scope Window	A waveform of analyzed data is displayed. It is displayed in the analysis mode.
b	Graph Window	Graphs of measurement and analysis data are displayed. Multiple pieces of [Graph Window] can be displayed, and switching of graph types, such as frame graph, trend graph, and 3D graph, is available.
c	Data Manager	The data file information handled by the O-Solution is listed. There are following two types of [Data Manager]. <ul style="list-style-type: none"> • Time Series Data Manager: The information of time series data file read into the O-Solution is listed. • Analysis Data Manager: The information of analysis data file read into the O-Solution is listed.

1.4.2 Measurement Mode



Item	Description
a	Measurement Manager Measurement related data is displayed. The displayed data varies depending on the measurement status. <ul style="list-style-type: none"> • During monitoring: List of data saved by the current settings • During measurement: List of data to be saved. When measurement ends, the data is confirmed and displayed. • During stop: List of data saved as a temporary file
b	Monitor Window A waveform of measured data is displayed. It is displayed in the measurement mode.
c	Progress Monitor The information such as elapsed time of recording, recordable time, remaining recording time, average count, and progress of analysis is displayed.
d	Level Monitor The input signal level is displayed. You can check or adjust the signal level.
e	Graph Window Graphs of measurement and analysis data are displayed. Multiple pieces of [Graph Window] can be displayed, and switching of graph types, such as frame graph, trend graph, and 3D graph, is available.

	Item	Description
f	Data Manager	<p>The data file information handled by the O-Solution is listed. There are following two types of [Data Manager].</p> <ul style="list-style-type: none">• Time Series Data Manager: The information of time series data file read into the O-Solution is listed.• Analysis Data Manager: The information of analysis data file read into the O-Solution is listed.

2. Equipment Connection Configuration Example

The following shows the types of Accelerometer and some cases of connection configuration. Each Accelerometer is connected to the input channel (from CH1) of the DS-5000 series Data Station.


Note that this manual describes the case 1 where a single unit of triaxial accelerometer is used.

● **Case 1: Using Ono Sokki NP-3000 Series Accelerometer (with Built-In Preamp) or the Like**

When the Accelerometer (with built-in preamp) is used, power can be supplied from the DS-5000 series Data Station to the sensor (CCLD).

Direct connection can be performed when the connector of the Accelerometer cable is a BNC connector.

For the case of miniature connector (UNF 10-32), a conversion adapter such as NP-2001 is used.




● **Case 2: Using Ono Sokki NP-2000 Series Accelerometer (Charge Output Type) or the Like**


Ono Sokki CH-6130/6140 Charge Converter or the like is used.

A conversion adapter such as NP-0021 cannot be used.


When the CH-6130/6140 Charge Converter is used, power can be supplied from the DS-5000 series Data Station to the Charge Converter (CCLD).



● **Case 3: Using Ono Sokki NP-3000 Series Accelerometer (with Built-In Preamp) or the Like and Ono Sokki PS-1300 Sensor Amplifier or the Like**



● **Case 4: Using Ono Sokki CH-1200A Charge Amplifier or the Like, Ono Sokki VC Series Vibration Comparator, or Other Vibrometers**



Memo

• For the case 3 and case 4, power is not supplied from the DS-5000 series Data Station to the sensor (CCLD disabled).

3. Preparation for Measurement

3.1 Preparing Measuring Instruments and Starting Software

Prepare the measuring instruments as described below.


1. Connect the measuring instruments.

Connect the Accelerometer, amplifier, etc. to the DS-5000 series Data Station with reference to the figure provided in "[2. Equipment Connection Configuration Example](#)".

2. Turn on the powers of the measuring instruments.

Connect the DS-5000 series Data Station with a personal computer using the LAN cable.

Then, turn on the power of each measuring instrument. For details about the power supply, refer to the instruction manual attached to each measuring instrument.




3. Turn on the power of the DS-5000 series Data Station.

Hold down the power switch of the DS-5100 Main Unit for one second or more. The power switch LED will turn on, and the power of the DS-5000 series Data Station will turn on.

4. Start up the O-Solution.

Click the start button, [Onosokki O-Solution], and [O-Solution] in this order to start up the O-Solution. You can also start up the O-Solution by double-clicking the O-Solution shortcut icon on the desktop. When the O-Solution is started, the [Selecting Project] dialog will be displayed first.




3.2 Creating New Project

● Creating New Project before Measurement

Create a new project before starting measurement.


When the O-Solution is started, the [Selecting Project] dialog will be displayed. Select [New project] (1), enter a project name (2) and then click the [Execute] button (3).



● Creating Project while Running the O-Solution

To create a project while running the O-Solution, select [New project] (1) from the [File] menu.


When the [Creating New Project] dialog is displayed, enter a project name (2) and then click the [Execute] button (3).



● Opening Saved Project

When a saved project exists, select [Open Project] (1) from the [File] menu.

When the [Open] dialog is displayed, select a target project file (2) and then click the [Open] button (3).



3.3 Connecting DS-5000 with O-Solution

When the preparation is done, make the DS-5000 series Data Station recognized by the O-Solution according to the following procedure.

1. Switch to the measurement mode.

Click the measurement mode icon () (1) to switch to the measurement mode.

2. Check the connection.

A connection with the DS-5000 series Data Station is established automatically by default.


When the connection is completed, the graphs of valid channels are arranged automatically in [Graph Window].

3. Check the hardware information.

Select [Hardware Connection] (2) from the [Input Settings] menu to display the [Hardware Connection] dialog.

Clicking the [Search] button (3) in the [Hardware Connection] dialog displays the hardware list.

After checking the information, click the [Close] button to close the dialog.



● Checking Hardware Information at Startup


When connecting the hardware, the hardware list can be displayed.

Select [Environment Settings] (1) from the [Edit] menu to display the [Environment Settings] dialog.

Click [Measurement] (2) in the [Environment Settings] dialog and check [Display hardware list when hardware is connected] (3).

Click the [OK] button (4) to close the dialog.

The hardware list will be displayed in the [Hardware Connection] dialog from the next attempt to connect the hardware.



3.4 Setting Channels

Set the input channels of the measuring instruments according to the following procedure.

1. **Display the [Input Condition Settings] dialog.**

Select [Input Condition Settings] (1) from the [Input Settings] menu.


2. **Set the channels.**

Check the check boxes of CH1 to 3 to be used (2) and then check the [CCLD] check boxes (3).

Uncheck the check boxes of other channels.

Enter a comment and DOF information (4) for each channel as needed.

When the setting is completed, click the [OK] button (5).



4. Unit Calibration

When the preparation for measurement is completed, perform unit calibration.


4.1 Setting Calibration

Set the signal type, sensitivity, and CCLD before starting measurement.

1. Display the [Calibration] dialog.

In the measurement mode, select [Calibration] from the [Input Settings] menu.

The [Calibration] dialog will be displayed.



2. Set the signal type.

Set [Signal type], [Unit], [EU type], and [EU value] in the [Calibration] dialog with reference to the calibration chart on the test certificate for the accelerometer.

Enter the sensitivity value, which is specified as the range (output sensitivity) for charge amplifier, etc., to [EU value].

It is specified as shown below in the calibration chart of Accelerometer. Refer to the value specified in the "Sensitivity @160 Hz" field.

Since the EU value is input in the unit of V, "0.001093" is entered for "1.093 mv".


In this section, the settings are configured as shown below. After completing the settings, click the [OK] button.

4. Unit Calibration

Item	Setting content
Signal type	Acceleration
Unit	m/s ²
EU type	V/EU
EU value	0.001093 (example)
CCLD	Check the check box (uncheck for the cases 3 and 4)

Voltage sensitivity (Sensitivity) @160Hz	<u>1.093 mV/ (m/S²)</u>
Bias voltage (Output Bias)	<u>10.4 VDC</u>

Refer to the value specified for "Voltage sensitivity (Sensitivity) @160 Hz".



- With [CCLD] checked, +24 V/4 mA is supplied from the checked channel to the Accelerometer, and the signal is input correctly.

5. Measurement Settings

5.1 Setting Time Axis Preprocessing

The time axis preprocessing function is used to process an acquired time waveform before performing frequency analysis.

For example, if an unnecessary noise component is mixed in the low frequency range, the noise can be removed by setting the digital filter.

You can also change the acceleration value to speed or displacement using the time axis calculus function.

In this section, the high-pass filter (HPF) is set to cut the frequency component of 10 Hz or lower as an example.

1. Display the [Time Axis Preprocessing] window.


In the measurement mode, select [Time Axis Processing] (1) from the [Input Settings] menu.

The [Time Axis Preprocessing] window will be displayed.

2. Set the high-pass filter.


Select [HPF] for [Digital filter] (2) in the CH1 row and enter "10.000" to [Lower limit frequency] (3).

Likewise, set CH2 and CH3.



5.2 Setting Measurement

Configure the channel and FFT related settings in the [Measurement Settings] dialog to perform frequency analysis. To display the [Measurement Settings] dialog, select [Measurement Settings] (1) from the [Measurement Control] menu in the measurement mode.




5.2.1 Setting Channels

Click the [Channel settings] tab (2) in the [Measurement Settings] dialog and set the channel related conditions.

Firstly, check the check boxes of CH1 to CH3 (3).

Since the measurement target this time is steady signal, [Hanning] is selected for [Window function] (4), and the DC cancel function is enabled to reduce DC component.

In this section, [DC cancel] is checked for each channel (5), and [Hanning] is selected for [Window function].




5.2.2 FFT Basic Settings

Click the [FFT basic settings] tab in the [Measurement Settings] dialog and set the FFT related conditions.

In this tab, items such as the number of sampling points and frequency range are set.

In this operation manual, the conditions are set as shown below.

Item	Setting content
Sample conditions	Internal (7)
Number of sampling points (number of analysis lines)	2048 (8)
Frequency range	Click [Frequency range (sampling frequency)] (9) and select [2.00kHz (5.12kHz)] (10).



One Point

- Increasing the value of [Number of sampling points (number of analysis lines)] makes the frequency resolution higher (Δf becomes smaller) for power spectrum, etc. However, the time (single frame window length) required to calculate the instantaneous power spectrum becomes longer, which causes poor followability to time variation.
For common vibration measurement, a value somewhere between 1024 and 4096 is set.


5.2.3 FFT Average/Detailed Settings

Click the [FFT average/detailed settings] tab (11) in the [Measurement Settings] dialog and set the averaging related conditions.

In this tab, select an averaging method in [Averaging settings]. Also, select either [Count] or [Time] for [Averaging conditions].

In this operation manual, the conditions are set as shown below.

Item	Setting content
Averaging method	Power spectrum summation averaging (12)
Averaging conditions	Time [s] (13)
Time [s]	10 (example) (14)




Memo

- For details about other selectable averaging settings, refer to "O-Solution Instruction Manual (Description of Functions)".

6. Graph Display Settings


Set the number of graphs displayed and the data types displayed in graphs.

To display [Graph Window], select [Graph Window] from the [Window] menu in the measurement mode.



6.1 Changing Graph Layout

Display a graph in [Graph Window]. In this section, the layout of 3 (horizontal) x 2 (vertical) is selected for display. To change the layout of [Graph Window], click the layout setting button on the toolbar in [Graph Window] and select the layout of 3 (horizontal) x 2 (vertical).




6.2 Displaying Channels in Graphs


After changing the graph layout, display the data of measured channels.

To display the measurement data in the graph area, drag a channel from [Measurement Manager] and drop it to the graph area.

The power spectra for three or six channels are displayed by default.



The channels are arranged as shown below.



6.3 Changing Data Types Displayed in Graphs


Change the data types displayed in graphs. In this section, the CH1 to CH3 graphs in the upper section and the CH1 to CH3 graphs in the lower section are changed to time axis waveform graphs and power spectrum graphs, respectively.

Follow the procedure below to change the data types.

1. Display the setting screen for the items displayed in graphs.


Click to select multiple graphs (CH1 to CH3 in the upper section) for which the data types are changed (1) while pressing the Ctrl key on the keyboard.

Then, click the [Item settings] button (2).



2. Change the data types of upper graphs (CH1 to CH3) to time axis waveform.

When [Item settings] is displayed, select [Time axis waveform] (3) at [Data type].




3. Check that power spectrum is displayed in the lower graphs (CH1 to CH3).

Power spectrum is selected as the graph data type by default.

Check that power spectrum is displayed for the lower graphs (CH1 to CH3).

When a data type other than power spectrum is set, set the graphs as shown below in the manner described above.




6.4 Setting Y Axis Display Unit and Scale

In this section, the Y axis display unit and display scale are set to [rms] and [Lin], respectively, for power spectrum graphs.

1. Display the axis settings.


Click the [Axis settings] button (1) on the option bar in [Graph Window].



2. Change the display scale.

Unfold [Y-axis settings] (2) first in [Axis settings].

Select [rms] (3) at [Spectrum units], and [Lin] (4) at [Scale].



- Either [Log] or [Lin] can be selected at [Display scale]. The following shows a relational equation between [Log] and [Lin].

$$10 \text{ Log (Lin value)}^2 = 20 \text{ Log (Lin value)}$$

Example: 6 (dB) for the case of Lin value = 2 (m/s²) when 0 dB reference value is 1


7. Temporary Measurement

Perform temporary measurement before main measurement to check that measurement can be performed normally. When there is no problem with temporary measurement, save the project and perform main measurement.

7.1 Setting Voltage Range

1. Display the [Level Monitor] screen.

In the measurement mode, select [Level Monitor] (1) from the [Window] menu.




2. Clear the over-range hold.

Firstly, click the [Clear Over Hold] button (2).

Then, check the check boxes of all channels (3) and select the minimum value at [Voltage range] (4).

7. Temporary Measurement




3. Check if an over-range occurs.

Start measurement to see if an over-range occurs.


For the channel in which an over-range occurred, click the [▼] button to raise the voltage range by one step. When using the medium mode, the button (▲▼) will be displayed by placing the cursor over the indicator. Return to the step 3 and clear the over-range hold. Then perform measurement again to see if an over-range occurs. Repeat this series of operations until no over-range occurs.

If you are worried about the occurrence of over-range, raise the voltage range by one step after adjustment.



● Changing Display Mode of Level Monitor

The display mode of [Level Monitor] can be changed in three steps: large, medium, and small by clicking the mode switching icons located in the bottom left section of the [Level Monitor] screen.



Mode	Description
Large mode	<p>In the large mode, channels are displayed in blocks in a column, with a single block containing six channels.</p> <ul style="list-style-type: none"> • Since this mode can display the largest amount of information for each channel, select this when you perform measurement for a small number of channels or you want to know the details of channels.
Medium mode	<p>In the medium mode, channels are displayed in blocks in two columns, with a single block containing six channels.</p> <ul style="list-style-type: none"> • Select this when you want to know the details of channels and also check a large number of channels at the same time.
Small mode	<p>In the small mode, channels are displayed using one block for one hardware unit.</p> <ul style="list-style-type: none"> • Select this when you want to know the channel statuses of individual measuring instruments at the same time. This is useful in measuring multiple channels.

7.2 Performing Temporary Measurement


In temporary measurement, the target is operated to adjust the voltage range and scale.

7.2.1 Starting/Stopping Temporary Measurement

Use the start and stop buttons on the toolbar on the main screen to start/stop temporary measurement.


After starting temporary measurement, check the voltage range on the [Level Monitor] screen. If a channel generating an A/D over exists, adjust the voltage range.

For the voltage range adjustment, refer to "7.1 Setting Voltage Range".



7.2.2 Adjusting Graph Scale

Adjust the Y axis display scale while checking the power spectrum waveform displayed in [Graph Window]. To adjust the graph scale, click the [Axis settings] button (1) in [Graph Window] to display [Axis settings]. Unfold [Y-axis settings] in [Axis settings] and enter values to [Maximum value] and [Minimum value] (2) to adjust the Y axis scale.



7.2.3 Saving Project

After the measurement conditions are determined in monitoring, save the project.

When a project is saved, the burdensome setting work can be omitted for the subsequent measurements having similar conditions.


One Point

- Note that even when you call a project, the voltage range needs to be adjusted before performing main measurement. For details, refer to "[7. Temporary Measurement - 7.1 Setting Voltage Range](#)".

● Project Saving Procedure

To save a project, select [Save Project As] (1) from the [File] menu.

Set the save folder (2) and file name (3) in the [Save As] dialog displayed and then click the [Save] button (4).



8. Main Measurement


When the preparation for measurement is completed, perform main measurement.

In this section, recording for ten seconds and power spectrum summation averaging for ten seconds are performed.

8.1 Toolbar Used in Main Measurement

Main measurement is operated via the toolbar on the main screen.

The buttons used for main measurement are as follows.



8.2 Setting Data Save

You can change the save methods for measured data, such as naming convention for files and automatic registration in [Data Manager].

In this section, the naming convention for files is set to "Data" (with sequential number), and a request for confirmation at registration in [Data Manager] is set.

1. Click to display the [Save Settings] dialog.

In the measurement mode, click [Save Settings] (1) from the [Measurement Control] menu.


2. Set the naming convention for files (2).

- Enter "Data" at [File name].
- Select [No.] at [Additional information].
- To change the beginning of serial numbers, enter a number in the [No.] field.
- You can check the actually assigned file name under the set conditions at [Output file name].

3. Request confirmation for recorded data when saving the file.

Check [Display confirmation dialog box before registering to Data Manager] (3).

When the setting is completed, click the [OK] button (4).




8.3 Performing Main Measurement

In main measurement, recording and analysis of power spectrum summation averaging are executed simultaneously.

Follow the procedure below to perform recording for ten seconds and analysis of power spectrum summation averaging for ten seconds.

1. Link recording with analysis.


Click the [▼] icon (1) on the right side of the start button and check [Link recording and analysis] (2).



2. Enable recording and analysis.


Click the recording button (3). Recording and averaging are enabled, and the buttons become active.

8. Main Measurement



3. Start main measurement.


Click the start button (4) to start measurement recording. Measurement recording stops after ten seconds.



 Memo


- When you click the stop button before ten seconds pass, measurement is stopped at that point. Even when measurement is stopped halfway, the recorded data and power spectrum summation averaging up to the stopped point are saved.
-

4. **When a confirmation message for saving recorded data is displayed, click the [Yes] button (5).**
Click the [No] button to discard the recorded data.



 Memo

- To register the recorded data in [Time Series Data Manager] automatically, uncheck [Display confirmation dialog box before registering to Data Manager] in the [Save Settings] dialog. Refer to "8.2 Setting Data Save".



8.4 Calculating Measurement Result

Perform double integration of calculus on the power spectrum averaged for ten seconds to convert the acceleration signal to displacement.

Follow the procedure below to perform double integration.

1. Display the setting screen for the items displayed in graphs.



Select the target power spectrum graph for double integration (1) and click the [Item settings] button (2).



2. Perform double integration.

Select [Double integral] (3) at [Frequency calculus].

The result of integration (4) will be displayed in the selected active graph.



8.5 Registering Data in Analysis Data Manager

1. Click the analysis data save button.

When measurement ends, click the analysis data save button (1) on the toolbar on the main screen.

2. Check the registration in [Analysis Data Manager].

The analyzed data will be registered in [Analysis Data Manager] (2).

The screenshot displays the Vibration_Ope software interface. The main window shows a Monitor Window with three channels (CH1, CH2, CH3) and their respective waveforms. A red circle with the number '1' highlights the analysis data save button in the toolbar. A blue callout box with the word 'Click' points to this button. The Analysis Data Manager window is open on the right side, showing a table of registered data files for three channels (CH_001, CH_002, CH_003). A red circle with the number '2' highlights the Analysis Data Manager window. The table in the Analysis Data Manager window is as follows:

File name	Item name
File	CH_001
File	CH_002
File	CH_003

9. Analysis Work

You can analyze recorded data in detail in the analysis mode.

9.1 Switching to Analysis Mode


Switch to the analysis mode to analyze recorded data.

1. **Switch to the analysis mode.**

Click the analysis mode button (1) on the toolbar on the main screen to switch to the analysis mode.

2. **Display the recorded data on [Scope Window].**


Drag and drop the recorded data from [Time Series Data Manager] to [Scope Window] (2).



3. **Check the waveform displayed at [Scope Window].**

The waveform of the recorded data (3) is displayed on [Scope Window].

Drag and drop all the analysis target data to [Scope Window] in the same manner.




9.2 Integration (Conversion from Acceleration to Displacement)

Performing double integration on the recorded acceleration signal enables conversion to displacement. Follow the procedure below to perform double integration on recorded data.

1. Display the [Time Axis Calculus] dialog.

In the analysis mode, select [Time Axis Calculus] (1) from the [Time Series Calculation] menu.



2. Execute the calculation.


Set the conditions on data manager in the [Time Axis Calculus] dialog as follows.

Check the target data for double integration (2), then select [Double integral] (3) at [Calculation type].

Check [Remove DC component before integration], then set the value for [Cutoff frequency [Hz]] and [Extreme value].

Select [Automatic conversion] (3) at [Unit conversion].


When the setting is completed, click the [Execute] button (4).



3. Check the calculation result.

The calculation result is added to [Time Series Data Manager] (_Calculus).

Drag and drop it to [Scope Window] (5) to check the result.



9.3 FFT Analysis

To perform FFT analysis on recorded data, select [FFT analysis] from the [Analysis Calculation] menu in the analysis mode.

You can configure the channel and FFT related settings in the [FFT analysis] dialog displayed.

For the setting method, refer to "[5.2 Setting Measurement](#)".

9.4 Comparing Power Spectra

Multiple graphs can be overlaid on one another in [Graph Window]. This allows you to compare the averaging results of multiple power spectra easily.




Memo


- The graphs displayed in [Graph Window] in the analysis mode need to be set separately. The operation procedure is the same as that in the measurement mode. Refer to "[6 Graph Display Settings](#)".

9.4.1 Overlaying Graphs

To overlay graphs, drag the cursor value of the channel 1 power spectrum graph (CH_001) and drop it on the channel 3 power spectrum graph (CH_003).



The graphs are overlaid on each other.




9.4.2 Checking Peak Value with Cursor

You can check a peak value with peak cursor.

To change to a peak cursor, select the target graph (1) and click the [Cursor settings] button (2) and then select [Peak cursor] (3) at [Cursor type].

A peak cursor (○) (4) will be displayed at a peak value.




9.5 Drawing Time Trend Graph

Follow the procedure below to set the graph type of channel 2 power spectrum graph (CH_002) to time trend graph.

1. Select a graph.

Select the channel 2 power spectrum graph (CH_002) (1) and click the [Graph area settings] button (2).




2. Switch to time trend graph.

Click the [Graph area settings] button and select [Trend Graph] (3) at [Graph type switching].


3. The graph will be switched to time trend graph.

The selected graph will be switched to the time trend graph (4).

9. Analysis Work




4



10. Saving Project

Save the created measurement conditions, graph display method, recording data, and analysis data together in a single project.

When you select [Save Project] from the [File] menu, the project will be saved by overwriting.



- When you want to save as a different project, select [Save Project As] from the [File] menu. The [Save As] dialog will be displayed. Set the save folder and file name in the [Save As] dialog and then click the [Save] button.

For details, refer to "7.2 Performing Temporary Measurement - 7.2.3 Saving Project".

11. Measurement Note

Note the necessary information for measurement in the following form.

Title	
Note	
Client	
Reference material	
Measurement date and time	
Person who performs measurement	
Measurement location	
Measurement method	
Measurement conditions	
Measuring instrument mode/settings	
Project name/ save destination	
Data name/ save destination	
Measuring instrument/sensor	
Calibration value	

DS-5000 series Data Station
O-Solution FFT Analysis Function
Operation Manual
Vibration Measurement

January 21, 2021, the first edition issued
April 20, 2021, the second edition issued
July 20, 2021, the third edition issued

Issued by:
ONO SOKKI CO., LTD.
3-9-3 Shin-Yokohama, Kohoku-ku, Yokohama 222-8507, Japan
Website: <https://www.onosokki.co.jp/English/english.htm>

Contact destination
ONO SOKKI CO., LTD. Overseas sales section
E-Mail: overseas@onosokki.co.jp
Phone: +81-45-476-9725

* The copyright of this manual belongs to Ono Sokki.

* Reproduction, distribution, etc. are prohibited except where necessary to use our products or stipulated by law.