

## Instruction Manual SD

**Model: SD, Spring Tester**



(For ON, press 1 sec.)


Thank you for buying a SAUTER Spring Tester. We hope you are pleased with your high quality force gauge with its big functional range. If you have any queries, wishes or helpful suggestions, do not hesitate to call our service number.

### 1. Working Conditions

10°C to 30°C / 15% up to 80% humidity


### 2. Operation

#### a. Display



- (1) Measuring Result
- (2) Measuring Units
- (3) Activation of PRINT Function
- (4) Indication of power charging status
- (5) PEAK or AUTO-PEAK Mode
- (6) Average value of stored peak values
- (7) Force direction
- (8) Occupancy of storing spaces
- (9) AVERAGE- or Saving Mode

#### b. Operating keys

ON / OFF: 

ON / OFF key

UNIT:



- Press shortly:

Select unit:  
N, kg or lb

ZERO:



Three functions:

- Zeros the measuring result (Tara function)
- Cleans the peak value (in Peak mode)
- Saves a setting (in SET mode)

SET:



- 1 x Press: Upper Limit [HidT]. To change press: ▲ or ▼ (see section c.)

HidT

- 1 x Press: Lower Limit [Lo dT]. To change press ▲ or ▼ (see section c.)

Lo dT

- 1 x Press: Minimum limit to save peak values in the instrument's memory. [LE.SET]. Please see section „Min Limit Peak Save“. To change press: ▲ or ▼ (Only in „Peak-Mode“active) (see section g.)

LESET

- 1 x Press: Auto-Off Function. Turns the instrument off after a here defined time period in sec. [P.OFF]. To change press: ▲ or ▼ (Only in „Battery-Mode“ active)

P.OFF

- 1 x Press: Peak-Freeze-Time [PE.2E / A.PE / HoldT]: Time period in which a peak value is being shown in the display in sec. To change press: ▲ or ▼



1 x Press: Saves the Settings

PEAK:



Three functions

- Track mode (continuous measurement)
- Peak mode (capture of maximum values)
- Auto-Peak mode, same as Peak-mode, only without the „Min limit peak save“ function

## Instruction Manual SD

**MEMORY:**



Saves the peak values to calculate the average value (please see section "Memory mode")

**DELETE Function**




Deletes stored peak values (only in „Memory mode“ active)

**PRINT:**



Sends the stored peak values to a PC or Printer (Please see section „Data Output“)



This function allows to eliminate unwanted „Pre-Peak values“ that are lower than the main peak value ( $F_P$ ). The „Min limit peak save“ value ( $F_0$ ) takes care, that these „Pre-Peak values“ are not saved.

The „Min limit peak save“ function is only in the Peak-Mode possible.

To set this Min limit value, please see the SET Menu in section „Operating keys“.

**c. High / Low limit function**

- ▲ HI Higher than higher limit
- OK OK
- ▼ LO Lower than lower limit

This function allows efficient testing of OK / NOT OK measurements of similar or identical testing objects. A lower and an upper limit value can be defined. The instrument compares the individual measuring results with these limit values and shows the OK or NOT OK result by green or red light diode and by sound. To set these limit values, please see the SET Menu in section „Operating keys“.

**d. Measurement (Track Modus)**

Display (1) shows the continuous force in a defined direction (6)

To zero the display, press:



**e. Peak-Hold Function (Peak Mode)**

Please press:



**f. Auto-Peak-Hold-Function (Auto-Peak Mode)**

Please press:



**g. Min limit peak save**

**h. Memory mode and average value** (from up to 10 peak values)

Saving peak values in the instrument

- ⇒ Activating the „AUTO PEAK Function“ by PEAK key
- ⇒ Deactivating the „Average Function“ by MEMORY key
- ⇒ Now, all peak values are stored automatically in the instrument
- ⇒ To browse through the stored values, please use the ▲ or ▼ keys. (The values will be shown in the upper display segment)
- ⇒ By pressing the MEMORY key, the average value of the stored peak values can be shown (in the upper display segment)
- ⇒ To delete every stored value, press the ▼-key in the AVERAGE-Mode

**3. Thread of the fine adjustment screw**

The following is valid for small Spring Testers (SD 10, 20,30) and those of medium size (SD 50, 100, 200, 300, 500):

The thread of the fine adjustment screw is a thread of DIN M6, the flank lead is respectively to this DIN, which is approximately 1mm per turn of the knurled nut.

**4. Printer output**

Below there are two pictures:

The first one shows the printer compartment closed, on the left side of the spring tester. The paper roll with the printed

## Instruction Manual SD

measurement results is sticking out, in the way it comes out of the small guide trench.

On the right side of the compartment you can find a small button, which has to be pressed to open the compartment for changing the paper roll.



The second picture, see below, shows the open paper roll compartment. It is shown how the paper roll has to be inserted correctly into the compartment for succeeding printing operations.

To close it, the button on the right has to be pressed during closing the compartment. A small piece of paper has to stick out.



Below you see the printing output with all necessary information:

Title	SD 500N100 TEST REPORT
Data for memo	DATE: -----
Number	NO:
Unit	UNIT:N
Upper Limit	HIDT:280.0
Lower Limit	LODT:260.0
Minimum Captured Value	LE.SET:10.0
Measuring Value/Data + is over upper limit, - is lower than lower limit, Ok is the eligible.	01 250.2 -
	02 278.3 ok
	03 250.5 -
	04 285.5 ok
	05 256.8 ok
	06 270.8 ok
	07 266.6 ok
	08 275.2 ok
	09 269.8 ok
	10 286.5 +
Max. Value	MAX:286.5
Min. Value	MIN:250.2
Average Value	AVERAGE:269.0

### 5. Warning

#### Intended use

The instrument you have acquired serves to determine the measuring value of the material to be measured. It is intended to be used as a "non-automatic" instrument, i.e. the material to be measured is manually and carefully attached at the instrument. The measuring value can be read off after a stable measuring value has been obtained.

#### Inappropriate use

Do not use the instrument for dynamic measuring. In the event that small quantities are removed or added to the material to be measured, incorrect measuring results can be displayed due to the "stability compensation" in the instrument. (Example: Slow draining off of liquid from a container suspended from the instrument). Do not attach a continuous load. This can damage the measuring unit as well as the parts, relevant to safety.

Prevent jolts, torsion and oscillation (e.g. by appending slopingly) of all kinds. Be sure to prevent overloading the instrument in excess of the stated maximum load (max.), minus any tare weight that may possibly exist. This could damage the instrument (risk of breakage).

#### Important:

- Always make sure that there are no people or materials below the load that could be injured or damaged!

Never operate the instrument in hazardous locations. The series design is not explosion-proof. Structural alterations may not be made to the instrument. This can lead to incorrect measuring results, faults concerning safety regulations as well as to destruction of the instrument. The instrument may only be used in compliance with the described guidelines. Varying areas of application/ planned use must be approved by SAUTER in writing.

#### Guarantee

The guarantee is not valid following

- non-observation of our guidelines in the operating instructions

## Instruction Manual SD

- use outside the described applications
- alteration to or opening of the device
- mechanical damage and damage caused by media, liquids
- natural wear and tear
- inappropriate erection or electric installation
- overloading of the measuring equipment

### 6. CE Declaration of conformity



**SAUTER GmbH**  
 D-72458 Albstadt  
 E-Mail: info@sauter.eu  
 Tel: 0049-[0]7431- 938-666  
 Fax: 0049-[0]7431-938-292  
 Internet: www.sauter.eu

#### Konformitätserklärung

Declaration of conformity for apparatus with CE mark  
 Konformitätserklärung für Geräte mit CE-Zeichen  
 Déclaration de conformité pour appareils portant la marque CE  
 Declaración de conformidad para aparatos con marca CE  
 Dichiarazione di conformità per apparecchi contrassegnati con la marcatura CE

**English** We hereby declare that the product to which this declaration refers conforms with the following standards.

**Deutsch** Wir erklären hiermit, dass das Produkt, auf das sich diese Erklärung bezieht, mit den nachstehenden Normen übereinstimmt.

**Français** Nous déclarons avec cela responsabilité que le produit, auquel se rapporte la présente déclaration, est conforme aux normes citées ci-après.

**Español** Manifestamos en la presente que el producto al que se refiere esta declaración está en acuerdo con las normas siguientes

**Italiano** Dichiariamo con ciò che il prodotto al quale la presente dichiarazione si riferisce è conforme alle norme di seguito citate.

#### Electrical spring tester: **SAUTER SD**

Mark applied	EU Directives	Standards
<b>CE</b>	89/336/EEC EMC 92/31 EC 93/68 EEC 2004/108 EC	EN 61326-1 :2008

Date: 13.05.2007

Signature: 

**SAUTER GmbH  
Management**

SAUTER GmbH, Schumannstrasse 33, D-72458 Albstadt, Tel: +49 (0) 7431 938 666, Fax: +49 (0) 7431 938 292